

中文題目:置放經靜脈心律調節器後的不尋常 QRS 波:如何加速正確診斷

英文題目: Unusual QRS morphology after trans-venous pacemakers: How to facilitate diagnosis

作者: 郭弘誼³, 李文煌¹, 林立人², 李貽恆¹, 陳儒逸^{1,*}

服務單位: 成大醫院內科部心臟血管內科¹成大醫學院生物藥學研究所² 成大醫院內科部³

Abstract

During right ventricular pacing, left bundle branch block (LBBB) can be expected. However when right bundle branch block (RBBB) develops after pacemaker implantation, malposition of the pacemaker lead should be first excluded. We report on an 87 years old woman having RBBB configuration after implantation of a trans-venous temporary pacemaker whose lead perforated intra-atrial septum and entered the left ventricle.